







Functionally, ePLM IDE was designed to provide a common enterprise product model capability (digital twin), facilitating bidirectional traceability (digital thread) to more efficiently manage the digital models throughout the lifecycle, and provide a common data decision environment to address escalating life cycle cost growth across the Navy.

## OPS NO.

## Leveraging the "Digital Twin" & "Digital Thread" Analysis, Modeling & Simulation

The "Digital Thread" serves as a "living" information rich environment, continually delivering information for Analysis, Modeling & Simulation (A, M&S) to influence critical design and support decisions across the lifecycle.

- Product data and associated information enables Reliability, Availability, Maintainability (RAM) and Product Support Analysis (PSA) analytics, processes and members all working from the same "sheet of music".
- Technical planning and decisionmaking in the IPTs where System Engineers and Product Support Teams collaborate.
- Resulting Changes update the configuration and derive the metrics of a new "digital thread".



OPS

## A Day in the Life of a Digitally Transformed PS Team Checkin' in with the Digital Twin

Somewhere in the World	Actions - ILibrary - UIC Library, EPLMIDE													
CVN 77 UAV CONOPS:	Folders (3 object	Folder Contents All	· .											
<u>UAV OPS RESTRICTED</u> : Intermittent loss of UAV	»	New Document New Part New Change Red	quest New Review New Folder	Copy Add to Workspace										
navigational control on final approach resulting in damage to	UIC Library	Number Name	NS (1)	Version State										
payload, landing gear and potential loss of UAV.	Documents	23170         CVN 77-GEORGE H	W BUSH	1 (Engineering) Active										
Initial indications at the O & I Level			D (j) PSHIRE (j)	1 (Engineering) Active										
a potential leading cause.		23173 CVN 78-GERALD R F	FORD (1)	1 (Engineering) Active										
Lets Start with our Digital	· • · · · · · · []	🔲 💸 23180 LPD 24-ARLINGTON	i.	1 (Engineering) Active										
Twin:	Details Structure Rela	ated Objects Changes History	Where Used Traceability											
1. Location of the Strike	Editing	Check Out/In	Clipboard View	ring New/Add To										
Talon UAV within the Fleet 2. Review the Thermostat	<ul> <li>Insert Existing — Remove</li> <li>Insert New • / Edit •</li> </ul>	Check Out 🏰 Revise	aste Copy Show -	Views  Views  New Add to										
Control	Find in Structure	All Advanced -												
3. Leverage the FRACAS Digital Thread	Identity		CAGE Code Number	Name										
0	▲ 23170, CVN 77-GEORGE I	H W BUSH, EPLMIDE,1 (Engineering) IKE TALON, EPLMIDE,3 (Engineering)	EPLMIDE 21660 EPLMIDE SYSTEM-00	CVN 77-GEORGE H W BUSH 0_01 STRIKE TALON										





	<b>jital ]</b> I: Failu	Chreac re Repor	<b>l in A</b> o ting An	ctio: alysis	n: 5 & Cori	recti <sup>.</sup>	ve Ao	ction Analy	rsis		Ар	proved f	or Publi Sli	c Releas de 9 of 2
urteen Trees Harms														_
Name R ASSEMBLY ANTE	И NNA RELAY	Part Number 104747-101 104747-102	Failure Rate, Predicted 45.036763 26.135814	MTBF, Predict 22204 38262	Failure Rate (FRACAS) 0.000000 0.000000	MTBF, Actual 0.000000 0.000000	Cost \$0.00 \$0.00	Parent Assembly UHF/SATCOM UHF/SATCOM	Manufacturer	Description UA/ Downlink	Configuration	Level 4 4	ESW85	FSC NI
	COOLING 5.2 AMP CONTROL	104747-AUX-109 104747-FAN-11 66F060-0431	32357.743714 25000.000000 7344.720274	31 40 136	0.000000	41.892992 0.000000 49.509900	\$9,310.00 \$0.00 \$0.00	UHF/SATCOM ASSEMBLY AUX COOLING ASSEMBLY AUX COOLING	Airpex Airpex Airpex	Thermostat		4 5 5	1	
System Tree Items	n er purations 📝 Proble	CD62450 CD66K97.34	6 00000	166667	0.00000	0.000000	60.00	ACCENTED AUX COOLING		REAY		5		
-	Site, Incident: System Tree Item: Serial Number: Meter Reading:	THERMOSTAT CO	Strike 1	ialon V V	CASREP Number: - 2Kilo Report When Discovered Co	1			Inci Inci Direct Suj Reference	dent ID: Inc002 dent Entry 12/08/2	1 1017 19	0 Atta	chments	
Contraction of the local division of the loc	Failure Symptom: Failure Detection: Operating Mode:	Overheating Operator Senses Normal Operation		~	Open Date of the Rep Status Code: Priority Code:			3	Details:	sification	- 8			
Description, Incident: Thermostat Fan Failed, replaced on site	Occurrence Date:	1/06/2012 Standard Remarks, Incident D Perform failure revi assign Failure Mode	Time To Failure: 41.00 ntry: ew and cetegorization & s e, Relevance, and Critical	coring to A	Action Taken Code: Work Center: EIC:				Failure Mode: Failure Classi Relevant Categ Charaeable Ca	fication:				> > >
Maintenance Log	~	folio	w-up Required (See FRB A	ctions)	CSMP Narrative:			0	Non Relevant ( Non Chargeab	Category:				~
Incident         Maintenanc           1         inc001         MaintEng1           * <click a="" here="" insert="" new="" record<="" td="" to=""></click>	e Log ID CASREP Nun	nber Maintenance Start 1/9/2012	Symptom Sub-As Overheating	sembly Part THERM	Deficient OSTAT FAN Short	cy Action Rplace	s Taken d Thermostat	Remarks Fan						

Sheen	PRODUCT	LIN ON	Digi	tal Th	read	in Ac	tion									Appr	oved for Public Release Slide 10 of 25
4100	PROCESS	NO.S.	RAM:	Failure 1	Report	ing Anal	lysis d	& Cor	recti	ive A	ctior	n Anal	ysi	s			
System	Tree Items																
Filter N	- 8			- 8	- 2	- 2	- 2	- 2			- 8	- 8	- 8	- 8			
	Name			Part Number	System Tree Id	enti Failure Rate, Predic	ted MTBF, Pred	icted MTBF	1 (FRACAS) Ref	erence Designa	Description	Manufacturer	MTTR (Mai.	Failure Rat	Parent Assembly		
	8	😺 R/T L	IHF SATCOM	104747-101	System70	45.0	36765	22204	0.000000 COM	MNA/11				# 0.000000	UHF/SATCOM		
	8	ASSE	MBUY ANTENNA RELAY	104747-102	System73	26.1	35814	38262	0.000000 000	MNA/12	UA/ Downli_			# 0.000000	UHF/SATCOM		
	6	ASSE	MBUY AUX COOLING	104747-AUX-1	09 System76	\$2357.7	43714	31 1	36.152224 COM	MNA/13		"MANUFACTU		# 0.000000	UHF/SATCOM		
		💭 F#	N COOLING 2 AMP	104747-6AN-1	10 System77	25000.0	00000	40	0.000000 COM	WNA/181		-MANUFACTU		# 0.000000	ASSEMBLY AUX COO	LING	
		🖓 TH	ERMOSTAT CONT	ROL 66F060-0431	System78	7344.7	20274	136 1	136.152224 COM	MNA/132	Thermostat	Airpax	:	# 0.000000	ASSEMIBLY AUX COO	LING	
		<b>R</b>	elar fan	CDE2450	System79	0.4	64000	2e+006	0.000000 COM	MNA/153	Relay			# 0.000000	ASSEMBLY AUX COC	LING	
		🤤 O	DOLING OUTLET	\$066587-24	System114	6.0	00000	166667	0.000000 COM	MNA/134				# 0.000000	ASSEMBLY AUX COO	LING	
		- Q 0	IL INLET	01-098232V	System116	0.0	20000	Se+007	0.000000 COM	MNA/135				# 0.000000	ASSEMBLY AUX COO	LING	
		- 🤤 н	LAT SUMP	23451-25	System115	0.0	00500	26+009	0.000000 COM	MNA/136	-	A/X Corporati		# 0.000000	ASSEMBLY AUX COC	LING	
		- C P	ENUM	NPRD-68756	System118	6.5	38939	152930	0.000000 COM	MNA/137				# 0.000000	ASSEMBLY AUX COO	LING	
	8	ASSE	MBLY UHF SATCOM	104747-CTRL-	111 System80	85.5	61774	11687	0.000000 CO	MNA/14				# 0.000000	UHF/SATCOM		
H	System Ire	e fierns	MEA TADIE	PMEA tree items - System	n 👘 KBD table 👔	ROU BIOCKS A FIA TO	ole 📝 Probler	8									4.5
ERACA	Incidente																
TIMUN	Sincidents			-											- 62		
riter C																	8
	Incident ide	enother	Occurrence Date	Description, Incident	Failure Mode	System	Component	Serial Numb	ter Closed?	Action Taken		Close Out End D	late	Time To Pail	Cumulative Failur	Problem	Parent Assembly
1	Inc001		1/6/2012	Thermostat Failed, replaced on site	Improper Output	ASSEMBLY AUX COOLING	THERMOSTAT	10234111	Ø	CHANGED OU	T THERMOSTAT	1/8/2012 5:41:4	16 PM	41.00	41.00	Thermostat Fan Failures	ASSEMBLY AUX COOLING
2 5	Inc002		8/4/2012	Thermostat Fan Failed r	Improper Output	ASSEMBLY ALLY COOLING	Thermostat Fan	10254112	P	CHANGED OUT	Thermostat Fa	n 8/12/2012 5:40	16 PM	30.00	70.0	Thermostat Fan Failu	ASSEMBLY AUX COOLING
3	Inc003		8/5/2012	Thermostat Fan Failed, r.	Electrical Overstre	ASSEMBLY AUX COOLING	Thermostat Fan	9521M02	2	CHANGED OU	T Thermostat Fa	n 8/8/2012 5:40.5	3 PM	20.00	90.0	Thermostat Fan Failu	ASSEMBLY AUX COOLING
4	Inc004		9/2/2012	Thermostat Fan Failed, r.	Improper Output	ASSEMBLY AUX COOLING	Thermostat Fan	10234143	2	CHANGED OU	T Thermostat Fa	n 9/2/2012 5:42:0	9 PM	15.00	105.0	Thermostat Fan Failu	ASSEMBLY AUX COOLING
5	Inc005		9/8/2012	Thermostat Fan Failed, r.	Electrical Overstre	ASSEMBLY AUX COOLING	Thermostat Fan	9521M02	2	CHANGED OU	T Thermostat Fa	n 9/9/2012 5:41:1	6 PM	12.00	117.00	Thermostat Fan Failu	ASSEMBLY AUX COOLING
6	Inc006		10/1/2012	Thermostat Fan Failed, r.	Improper Output	ASSEMBLY AUX COOLING	Thermostat Fan	10234156	Ø	CHANGED OU	T Thermostat Fa	in 1/3/2014 5:39 5	64 PM	10.00	127.00	Thermostat Fan Failu	ASSEMBLY AUX COOLING
7	Inc007		11/17/2012	Thermostat Fan Failed, r.	Electrical Overstre	ASSEMBLY AUX COOLING	Thermostat Fan	9521MD2	8	CHANGED OU	T Thermostat Fa	in 11/18/2012 5:4	0:53 PM	8.00	135.00	Thermostat Fan Failu	ASSEMBLY AUX COOLING
8	Inc008		11/18/2012	Thermostat Fan Failed, r.	Improper Output	ASSEMBLY AUX COOLING	Thermostat Fan	10234112	2	CHANGED OU	T Thermostat Fa	n 11/19/2012 5:4	0:53 PM	10.00	140.00	Thermostat Fan Failu_	ASSEMBLY AUX COOLING
9	Inc009		1/8/2013	Thermostat Fan Failed, r.	Disconnected	ASSEMBLY AUX COOLING	Thermostat Fan	9521M02		RECONNECTER	D PWR CABLESS	1/10/2013 5:40	53 PM	42.00	182.00	)	ASSEMBLY AUX COOLING
10	Inc010		3/13/2013	Thermostat Fan Failed, r.	Unknown	ASSEMBLY AUX COOLING	Thermostat Fan	10234111	0	CHANGED OU	T Thermostat Fa	in 3/15/2013 5:40	53 PM	9.00	191.00		ASSEMBLY AUX COOLING
11	Inc011		10/1/2013	Thermostat Fan Failed, r.	Disconnected	ASSEMBLY AUX COOLING	Thermostat Fan	9521M02		RECONNECTED	PWR CABLESS	10/2/2013 5:40	53 PM	12.00	203.00	5	ASSEMBLY AUX COOLING
12	Inc012		2/1/2014	Thermostat Fan Failed, r.	Electrical Overstre	ASSEMBLY AUX COOLING	Thermostat Fan	10234143	2	CHANGED OU	T Thermostat Fa	in 2/7/2014 5:40.5	IS PM	17.00	220.00	0	ASSEMBLY AUX COOLING
13	inc013		6/11/2014	Thermostat Fan Failed, r.	Electrical Overstre	ASSEMBLY AUX COOLING	Thermostat Fan	9521M02	Ø	CHANGED OU	T Thermostat Fa	n 6/13/2014 5:40	53 PM	15.00	235.00	0	ASSEMBLY AUX COOUNG
14	Inc014		11/7/2014	Thermostat Fan Failed, r.	Electrical Overstre	ASSEMBLY AUX COOLING	Thermostat Fan	10234156	Ø	CHANGED OU	T Thermostat Fa	in 11/9/2014 5:40	53 PM	10.00	245.00	0	ASSEMBLY AUX COOLING
15	Inc015		12/4/2014	Thermostat Fan Failed, r.	Disconnected	ASSEMBLY AUX COOLING	Thermostat Fan	9521M02		RECONNECTED	D PWR CABLESS	12/15/2014 5:4	0:53 PM	8.00	253.00	)	ASSEMBLY AUX COOUNG
16	inc016		1/1/2015	Thermostat Fan Failed, r.	Inoperative	ASSEMBLY AUX COOLING	Thermostat Fan	10234112		CHANGED OU	Thermostat Fa	in 1/3/2015 5:39:5	64 PM	9.00	262.00		ASSEMBLY AUX COOLING
17	Inc017		3/26/2015	Thermostat Fan Failed, r.	Inoperative	ASSEMBLY AUX CODUING	Thermostat Fan	9521M02	0	CHANGED OU	T Thermostat Fa	in 3/31/2015 5:43	15 PM	18.00	280.00	1	ASSEMBLY AUX COOLING

	FMEA	Worksheet														0	00
	Filter							.8			.8			18			
FMECA: Evaluation of the		Iten Identi.	Function	Functional Fa	Name	Mode Identif	Failure Mode	Mode Perc	Local Effect	Next Effect	End Effect	Cause of Failure	Severity	Occu.	Detecti	RPN M	lode Critic
extended effects of	9				1000	Mode109	Reduced Engine Cooling Flow	34.0	Engine Overheats	Reduction of UAV Hours	Mission Failure					0	9416.07
failures resulting in the	10	item1	Provide airflow to maintain	F/2P adequate	FAN COOLING 2	Mode1	8inding/Sticking	60.0	Cooling fan does not spin	COM/NAV gear overheats	Loss of UAV nev(gational control	Contamination	CATEGORYI	2	8	160	28.54
loss of functionality that	11		heat	wohnie	AMP	Mode3	Improper Output	30.0	Reduced COM/NAV Cooling Flow	COM/NAV gear overheats	Loss of UAV navigational con	Contamination	CATEGORY I	1	8	80	14.27
directly impacts the ability	12	-	transfer		-	Mode4	Improper Current	10.0	Will not start, intermittent oper	COM/NAV gear overheats	Loss of UAV navigational con	Connection Problem	CATEGORY I	1	8	80	4.76
of the system to meet requirements.	13	lten3	Provide airflow to maintain heat trans.	F/2 P adequat	THERMOS Fan	Mode5	Improper Output	100.0	Reduced COM/NAV Cooling Flow	COM/INW gear overheats	Loss of UAV nevigational con	Out of Adjustment	CATEGORYI	4	5	200	63.13
<ul> <li>Failure Modes listed by function or system component</li> <li>Analysis to determine next and higher level effects as well as qualitative and quantitative criticality assignment.</li> </ul>	14	Пет91	AUX Cooling maintains operating temp of COM/NA/ systems	Failure to maintain operating temp of COM/NAV systems	RELAY FAN	Mode98	Shorted Relay Fan	U	Re Inoperable	COM/NW gear overheats	Loss of UA/ navigational control	Water intrusion	CATEGORY III	3	3	36	0.64
	15	lten4	Direct and expel heat from syst	F/2 direct and expel heat fro	COOUING OUTLET	Mode6	Restricted Dutlet	100.00	Reduced COM/NAV Cooling Flow	COM/INAV gear overheats	Loss of UA/ nevigational con	Blocked or damaged outlet from Foreign Object Debris	CATEGORYI	9	6	540	8640.00
	16	iten5	Dissipate Heat from COM/NA/_	F/2 dissipate heat from COM/NAV com.	HEAT SUMP	Mode7	Disconnected Sump	100.0	COM/NAI component not cooled	COM/NAV gear overheats	Loss of UA/ navigational con	Excessive vibration loosens heat sump	CATEGORY III	1	2	8	36.00















CE C Model	<b>Curve: Incre</b> ling the Cost of 2	ea Ava	sing System Reliability				
Collaboration by	File Edit View Data Ioo	ls <u>W</u> i	ndow Help Al 31 livo ov Briter Bo So Ab Dy Priettine at Al 2005, Brita	( 92 kg			
		[] te	m Results			A*	В
Product Support	Open File ^					EMARSS 02012015-reall	EMARSS 0201201
	e- Input		1.4		11	1	26
and Engineering	B S Model View		© Item 922,1972,002	THE Station	P	STSIZ	STSIZ
	ProblemDescriptic     ControlParameter	38.	RECEIVER, DEFENSE ADVANCED GPS (DAGR), ROCKWELL COLLINS			0	
	GlobalParameters	76.	WB-86-WT-USB	-		0	
Evaluato	Control	58	CMDC-SW-DP			0	
Lvaluate	III Item		LNA FOR BLUFRCETRKR PATH, COMTECH-RCVR-PRCSR RT-1808A			-	
provisioning	ItemStructure	68.	MILSATCOM RADIO, AN/ARC-231	-		0	
	Station Station	57.	CF-74 LAPTOP, TOUGHBOOK MODEL 51	-		0	
/spares based on	SystemDeploymer	50.	8475426-2			0	
austom roliobility	ItemRepair	26	428-01569-004			-	
system reliability	ItemReorder	20.	WIRELESS MOD WPM-3A SRU				
	MissionType	15.	RADIO, MULTIMISSION, AN-PRC117G			0	
	OperationProfile	23.	400-10680-002 TRANSCEIVER IRIDU IM	-		0	
	ResultCollectionPi	27	428-01640-001			0	
	ScaleFactors		FILTER ASSY 11-1901026			-	
	Besource	13.	BYPASS SLOT BOARD, A17			0	
	ResourceAllocatio	70.	S65-8282-301 ANTENNA, L-BAND	-		0	
	Result	33.	525-00055			0	
	B- D Input		S-290E-AIR-COT			-	
	B Model View	69.	MAKITO ENCDR-Video	-		2	
	ControlParameter	71.	ANTENNA, RHCP AND LHCP (I/T)	-		0	
	GlobalParameters	29.	428-01758-002	-		0	
	System	14	1202C-0202				
	····· III Item	1-4.	PROCESSOR, COMINT, DRT 1202C				
	ItemStructure Station	64.	ENCRYPTOR, KG-175D TACLANE MICRO	•		0	
	StationStructure	19.	1541-A-2000 PRCSB-INTGRTD PWB-I NA-DIPLXB	-		2	
	SystemBenzir	56	C-12608			0	
	ItemRepair		RMTE-FILL-PNL-CNTRL RX/TX C-12608_01 12-210P98			Ű	
	ItemReorder	17.	ANTENNA, DF ARRAY AND ACQ HIGH BAND			0	
	MissionType	47.	8475424-1 MIO MODULE ASSY, A10			0	
	OperationProfile	44.	8473079-1 601/0550 0401/5 657			2	
	ResultCollectionPi	10	109289-01			_	
	ScaleFactors	10.	ANTENNA TO FPU			0	
	StockExist	49.	6475426-1 GENERAL PURPOSE PROCESS CARD MODULE ASSY: A1, A2, A16			0	
	<	29	428-01640-003			0	

	Curv	e: Readiness I	Base	ed S	par	in	g								
Model the overall	Part Number	Description	Unit Price	85. Total Cost	37% Readiness FRT [1/MHour]	QTY	89. Total Cost	91% Readiness FRT [1/MHour]	QTY	94. Total Cost	83% Readiness FRT [1/MHour]	QTY	97. Total Cost	04% Readiness FRT [1/MHour]	QTY
system Life	TOTAL COST			\$5,613,332.78			\$6,212,884.78			\$7,399,595.78			\$8,723,773.78		
System Life	SS100, INVERTER	, 115VAC ,60HZ, 1PHASE	\$4,272.00	\$0.00	101.010101	0	\$0.00	101.010101	0	\$4,272.00	101.010101	1	\$4,272.00	101.010101	1
Support Costs	1215-20, INVERT	R, 115VAC, 60HZ, 1 PHASE	\$5,492.00	\$0.00	101.010101	0	\$0.00	101.010101	0	\$0.00	101.010101	0	\$0.00	101.010101	0
	EMR01EZ0040-003	INSTL, WIRE HARNESS, INTERNAL CABIN, EMD	\$738.00	\$26,568.00	11427.36	36	\$26,568.00	11427.36	36	\$27,306.00	11427.36	37	\$28,044.00	11427.36	38
critical to	GB001_W05110-11	_EMR01EZ0045, GEOMETRICAL BUNDLE, INSTL, WIRE HARNESS. AFT FUSELAGE	\$738.00	\$0.00	34.01244856	0	\$0.00	34.01244856	0	\$0.00	34.01244856	0	\$0.00	34.01244856	0
achieving Ao:	GB001_W05110-11	EMR01EZ0045, GEOMETRICAL BUNDLE, INSTL, WIRE	\$738.00	\$0.00	34.01244856	0	\$0.00	34.01244856	0	\$0.00	34.01244856	0	\$0.00	34.01244856	0
Level of Repairs	GB001_W20196_EM	01EZ0045, GEOMETRICAL BUNDLE, INSTL, WIRE HARNESS,	\$728.00	\$0.00	24 01244956	0	\$0.00	24.01244955	0	\$0.00	24 01244956	0	\$0.00	24 01244955	0
Analysis by	\$125.A02.SE.S	DS SDUTTER 192	\$756.00	\$226.00	5 5620028	1	\$226.00	5 5620029	1	\$672.00	5 5620028	2	\$672.00	5 5620029	2
location	D12198-003 HEA	SET IRIDIUM	\$675.00	\$675.00	65 98917777	1	\$675.00	65 98917777	1	\$675.00	65 98917777	1	\$675.00	65 98917777	1
location	42228-05, HAND	ONTROLLER for MX-15HDi FOIR Sensor	\$10,140,00	\$0.00	50	0	\$0.00	50	0	\$0.00	50	0	\$0.00	50	0
<ul> <li>Snares by</li> </ul>	8408990-1, GPS.	C-MIGITS III	\$33,034,00	\$0.00	106.3829787	0	\$0.00	106.3829787	0	\$0.00	106.3829787	0	\$0.00	106.3829787	0
opuresby	\$65-8282-301GY.	ANTENNA, RHCP AND LHCP (I/T)	\$3,958.00	\$0.00	20	0	\$0.00	20	0	\$0.00	20	0	\$0.00	20	0
Readiness and/	109279-01, ANTE	NA, PHASED ARRAY	\$166,291.00	\$166,291.00	40	1	\$166,291.00	40	1	\$166,291.00	40	1	\$166,291.00	40	1
or by location	\$65-8282-301, A	TENNA, L-BAND	\$3,958.00	\$3,958.00	20	1	\$3,958.00	20	1	\$7,916.00	20	2	\$7,916.00	20	2
of by location	AT11M-10-TF, AT	ENUATOR, 10DB	\$150.00	\$150.00	7.919976557	1	\$150.00	7.919976557	1	\$150.00	7.919976557	1	\$150.00	7.919976557	1
	EMR01M13840-101	CABIN RF SWITCH PANEL	\$500.00	\$500.00	2.366701457	1	\$500.00	2.366701457	1	\$500.00	2.366701457	1	\$500.00	2.366701457	1
	HFB075100A, BAL	N (SINGLE)	\$800.00	\$0.00	6.666711111	0	\$0.00	6.666711111	0	\$0.00	6.666711111	0	\$0.00	6.666711111	0
	HFB075100B, BAL	N (DUAL)	\$800.00	\$800.00	13.33333333	1	\$0.00	13.33333333	0	\$800.00	13.33333333	1	\$800.00	13.33333333	1
	01-01664-001, A	TENNA, CRPA	\$66,593.00	\$66,593.00	66.66666667	1	\$66,593.00	66.66666667	1	\$66,593.00	66.66666667	1	\$133,186.00	66.66666667	2
	10553-1300-02,	N/PRC-117 RADIO KEYBOARD DISPLAY(KDU) FALCON III	\$492.00	\$492.00	7.939973798	1	\$492.00	7.939973798	1	\$984.00	7.939973798	2	\$984.00	7.939973798	2
	FAM-142A, AMPLI	ER, DUAL BIDIRECTIONAL, METROPOLE	\$15,390.00	\$0.00	200	0	\$0.00	200	0	\$0.00	200	0	\$0.00	200	0
	12-210P98, ANTE	NA, DF ARRAY AND ACQ HIGH BAND	\$10,000.00	\$30,000.00	20	3	\$30,000.00	20	3	\$30,000.00	20	3	\$30,000.00	20	3
	015-10306-001,	NTENNA, IRIDIUM	\$635.00	\$1,270.00	20	2	\$1,270.00	20	2	\$1,270.00	20	2	\$1,270.00	20	2
	AV201-10, ANTEN	A, FM/VHF/UHF/EPLRS/L-BAND	\$3,571.00	\$3,571.00	20	1	\$3,571.00	20	1	\$7,142.00	20	2	\$7,142.00	20	2
	DM NI50-10-2, A	TENNA, DM N150-10-2, IFF	\$200.00	\$200.00	40	1	\$200.00	40	1	\$200.00	40	1	\$200.00	40	1
	EMR01M13860-101	CABIN ZEROIZE PANEL	\$500.00	\$500.00	8	1	\$500.00	8	1	\$1,000.00	8	2	\$1,000.00	8	2
	SW-22050, CONVE	TER, VGA-NTSC VIDEO	\$50.00	\$100.00	100	2	\$100.00	100	2	\$100.00	100	2	\$100.00	100	2
	55LS1-012M1, CO	VERTER, 28VDC TO 12VDC	\$1,932.00	\$0.00	16.66666667	0	\$0.00	16.66666667	0	\$0.00	16.66666667	0	\$1,932.00	16.66666667	1
	3313-AS-450-1,	ONTROL INDICATOR, AAR-57	\$260,081.00	\$0.00	35.999712	0	\$0.00	35.999712	0	\$260,081.00	35.999712	1	\$260,081.00	35.999712	1
	31-200341-01, D	TECTING SET CONTROL	\$6,038.00	\$6,038.00	13.89004639	1	\$6,038.00	13.89004639	1	\$6,038.00	13.89004639	1	\$6,038.00	13.89004639	1
	FA002_EMR01EZ00	5, FASTENER ASSEMBLY, INSTL, WIRE HARNESS, AFT FUSELAGE	\$1,000.00	\$0.00	34.01244856	0	\$0.00	34.01244856	0	\$0.00	34.01244856	0	\$0.00	34.01244856	0
	MC-10901-2, ENC	YPTOR, KG-175D TACLANE MICRO	\$9,900.00	\$0.00	21.87417972	0	\$0.00	21.87417972	0	\$0.00	21.87417972	0	\$0.00	21.87417972	0

**OPS** 

## **CE Curve: Readiness Based Sparing** Modeling Readiness by Location Alternatives

		1			1		1				1	
Model the overall					95 27% Pog	diness	99 91% Pop	dinoss	0/1 92% Pog	dinoss	97.04% Poor	diness
avators Life Current	Part Number	Description	Unit Price	Stock Location	RPAPY	OTY	RPAPY	OTY	RPAPY	OTY	RPAPY	OTY
system Life Support	AT11M-10-TF, AT	ENUATOR, 10DB	\$ 150.00	FIELD LOCATION	1	0		1		1		1
Costs critical to	AT11M-10-TF, AT	ENUATOR, 10DB	\$ 150.00	DEPOT	5.439313179	1	5.44E-02	0	5.44E-02	0	5.44E-02	0
	EMR01M13840-101	CABIN RF SWITCH PANEL	\$ 500.00	FIELD LOCATION	1	1		1		1		1
achieving Ao:	EMR01M13840-101	CABIN RF SWITCH PANEL	\$ 500.00	DEPOT	1.625412693	0	1.63E-02	0	1.63E-02	0	1.63E-02	0
	HFB075100A, BAL	N (SINGLE)	\$ 800.00	FIELD LOCATION	0	0		0		0		0
<ul> <li>Level of Repairs</li> </ul>	HFB075100A, BAL	N (SINGLE)	\$ 800.00	DEPOT	4.578590523	0	4.58E-02	0	4.58E-02	0	4.58E-02	0
Analysis hy	HFB075100B, BAL	N (DUAL)	\$ 800.00	FIELD LOCATION	1	0		0		1		1
, and you by	HFB075100B, BAL	N (DUAL)	\$ 800.00	DEPOT	0.183142399	1	0.1831424	0	0.1831424	0	0.1831424	0
location	01-01664-001, A	TENNA, CRPA	\$ 66,593.00	FIELD LOCATION	1	0		1		1		2
	01-01664-001, A	TENNA, CRPA	\$ 66,593.00	DEPOT	0.457856000	1	0.457856	0	0.457856	0	0.457856	0
<ul> <li>Spares by</li> </ul>	10553-1300-02,	N/PRC-117 RADIO KEYBOARD DISPLAY(KDU) FALCO	\$ 492.00	FIELD LOCATION	1	1		1		2		2
Readiness and/or	10553-1300-02,	N/PRC-117 RADIO KEYBOARD DISPLAY(KDU) FALCO	\$ 492.00	DEPOT	5.453046964	0	5.45E-02	0	5.45E-02	0	5.45E-02	0
Reduiness and/ of	FAM-142A, AMPLI	ER, DUAL BIDIRECTIONAL, METROPOLE	\$ 15,390.00	FIELD LOCATION	0	0		0		0		0
by location	FAM-142A, AMPLI	ER, DUAL BIDIRECTIONAL, METROPOLE	\$ 15,390.00	DEPOT	1.3735680	0	1.373568	0	1.373568	0	1.373568	0
by location	12-210P98, ANTE	NA, DF ARRAY AND ACQ HIGH BAND	\$ 10,000.00	FIELD LOCATION	3	1		3		3		3
	12-210P98, ANTE	NA, DF ARRAY AND ACQ HIGH BAND	\$ 10,000.00	DEPOT	1.3735680	1	1.3/3568	0	1.3/3568	0	1.3/3568	0
	015-10306-001,	NTENNA, IRIDIUM	\$ 635.00	FIELD LOCATION	2	1	0 10705 60	2	0 10705 60	2	0 10705 60	2
	013-10300-001, AV/201_10_ANITEN		\$ 035.00	DEPUT	0.13735080	1	0.1373508	1	0.1373508	2	0.1373308	2
	AV201-10, ANTEN	A FM/VHE/UHE/EDLBS/L BAND	\$ 3,371.00	DEPOT	1 12725690	1	0 1272569	1	0 1272569	2	0 1272569	2
	DM NI50-10-2 A	TENNA DM N150-10-2 JEE	\$ 200.00	EIELD LOCATION	1	0	0.1373508	1	0.1373508	1	0.1373308	1
	DM NI50-10-2, A	TENNA DM N150-10-2, IFF	\$ 200.00	DEPOT	0 54942720	2	0 5494272	0	0 5494272	0	0 5494272	0
	EMR01M13860-101	CABIN ZEROIZE PANEL	\$ 500.00	FIELD LOCATION	1	1	0.0404272	1	0.0404272	2	0.0454272	2
	EMR01M13860-101	CABIN ZEROIZE PANEL	\$ 500.00	DEPOT	0.054942720	0	0.05494272	0	0.05494272	0	0.05494272	0
	SW-22050, CONVE	TER, VGA-NTSC VIDEO	\$ 50.00	FIELD LOCATION	2	1		2		2		2
	SW-22050, CONVE	TER, VGA-NTSC VIDEO	\$ 50.00	DEPOT	0.6867840	2	0.686784	0	0.686784	0	0.686784	0
	55LS1-012M1, CO	VERTER, 28VDC TO 12VDC	\$ 1,932.00	FIELD LOCATION	0	0		0		0		1
	55LS1-012M1, CO	VERTER, 28VDC TO 12VDC	\$ 1,932.00	DEPOT	0.114463536	0	0.114463537	0	0.114463537	0	0.114463537	0
	3313-AS-450-1,	ONTROL INDICATOR, AAR-57	\$ 260,081.00	FIELD LOCATION	0	0		0		1		1
	3313-AS-450-1,	ONTROL INDICATOR, AAR-57	\$ 260,081.00	DEPOT	0.247240262	1	0.247240262	0	0.247240262	0	0.247240262	0
	31-200341-01, D	TECTING SET CONTROL	\$ 6,038.00	FIELD LOCATION	1	0		1		1		1
	31-200341-01, D	TECTING SET CONTROL	\$ 6,038.00	DEPOT	9.539461619	1	9.54E-02	0	9.54E-02	0	9.54E-02	0
	FA002_EMR01EZ00	5, FASTENER ASSEMBLY, INSTL, WIRE HARNESS, AFT	\$ 1,000.00	FIELD LOCATION	0	0		0		0		0
	FA002_EMR01EZ00	5, FASTENER ASSEMBLY, INSTL, WIRE HARNESS, AFT	\$ 1,000.00	DEPOT	0.233592054	0	0.233592055	0	0.233592055	0	0.233592055	0
	MC-10901-2 ENC	VPTOR KG-175D TACLANE MICRO	\$ 9,900,00	FIFLDLOCATION	0	0		0		0		0











